

電磁接触器(可逆形)

単位：mm

外形寸法	穴明寸法	接点構成図
MR-50HA Technical drawing of MR-50HA showing front, side, and detail views with dimensions. Dimensions include 128, 58, 12, 23.4, 11.8, 56, 92, 13, 21, 50, 25, 9, 12.2, 14.8, 14.8, 13.1, 8.2, 111, 79, 45, 4.5, 85, 9, 94, 120, 88, 4, 70, 10.5, 70, 75, 4-M4取付穴, 最小9, コイル端子M3.5, 主接点端子M5, 補助接点端子M3.5, スライダ. (1.43kg)	Technical drawing of MR-50HA showing mounting hole dimensions. Dimensions include 50, 20, 50, 10.5, 70, 75, 4-M4取付穴.	Contact configuration diagram for MR-50HA showing F and R terminals. The diagram shows the following connections: F: A1 1 L1 3 L2 5 L3 13 NO 21 NC; A2 2 T1 4 T2 6 T3 14 NO 22 NC; R: A1 1 L1 3 L2 5 L3 13 NO 21 NC; A2 2 T1 4 T2 6 T3 14 NO 22 NC. The diagram also indicates 補助接点(1a1b)× 2.